

Message

From: Mitchell Martin [mmartin@greenleaf-power.com]
Sent: 9/3/2020 11:38:59 PM
To: Chew, Andrew [Chew.Andrew@epa.gov]; AEO_R9 [AEO_R9@epa.gov]; Jim Robertson [jrobertson@desertviewpower.com]
CC: Connolly, Scott [Connolly.Scott@epa.gov]; TLiebel@aqmd.gov; Kdudash@aqmd.gov; Greg Cook [gcook@greenleaf-power.com]; Ward, Laweeda [WARD.LAWEEDA@EPA.GOV]; Mark Boucher [mboucher@greenleaf-power.com]
Subject: RE: Desert View Power Permit No. CB-OP 99-01 - 10 working day follow up to 48 hr. Notification Excess HCl Emissions. Annual Boiler MACT Compliance Test

Andrew,

Please try the link below **Ex. 6 Personal Privacy (PP)**


Dropbox is giving me issues today, my apologies. Hopefully this works.

Ex. 6 Personal Privacy (PP)

Mitchell
(916) 596-2514

From: Chew, Andrew <Chew.Andrew@epa.gov>
Sent: Thursday, September 03, 2020 10:55 AM
To: Mitchell Martin <mmartin@greenleaf-power.com>; AEO_R9 <AEO_R9@epa.gov>; Jim Robertson <jrobertson@desertviewpower.com>
Cc: Connolly, Scott <Connolly.Scott@epa.gov>; TLiebel@aqmd.gov; Kdudash@aqmd.gov; Greg Cook <gcook@greenleaf-power.com>; Ward, Laweeda <WARD.LAWEEDA@EPA.GOV>; Mark Boucher <mboucher@greenleaf-power.com>
Subject: RE: Desert View Power Permit No. CB-OP 99-01 - 10 working day follow up to 48 hr. Notification Excess HCl Emissions. Annual Boiler MACT Compliance Test

Thanks for your e-mail, Mitchell. It appears that the password you sent 'DVPenviro2020' is not working. Here's a screenshot. Thanks for looking into this.



Enter the password for this link

Password

Incorrect password

Continue

- Andrew

Andrew Chew, P.E.

chew.andrew@epa.gov

U.S. EPA, Region 9, Enforcement & Compliance Assurance Division (ECAD), Air Section (ENF-2-1) | 75 Hawthorne St.,
San Francisco, CA 94105

From: Mitchell Martin <mmartin@greenleaf-power.com>

Sent: Thursday, September 3, 2020 5:19 AM

To: AEO_R9 <AEO_R9@epa.gov>; Jim Robertson <jrobertson@desertviewpower.com>

Cc: Connolly, Scott <Connolly.Scott@epa.gov>; TLiebel <TLiebel@aqmd.gov>; Kdudash <Kdudash@aqmd.gov>; Greg Cook <gcook@greenleaf-power.com>; Chew, Andrew <Chew.Andrew@epa.gov>; Ward, Laweeda <WARD.LAWEEDA@EPA.GOV>; Mark Boucher <mboucher@greenleaf-power.com>

Subject: RE: Desert View Power Permit No. CB-OP 99-01 - 10 working day follow up to 48 hr. Notification Excess HCl Emissions. Annual Boiler MACT Compliance Test

Andrew,

Please use the revised link below:

Ex. 6 Personal Privacy (PP)

Password: Ex. 6 Personal Privacy (PP)

Summary results for the HCl tests can be found on Table 4-1 and Table 4-5 of 'W002AS-678786-RT-1264-Part1'.

Please let me know if you have any issues with accessing the files and I can try another method. The final report is in 2 parts, both are 15-17 MB. If your email system can receive an attachment that large, I can just forward that way as well.

Mitchell
(916) 596-2514

From: AEO_R9 <AEO_R9@epa.gov>
Sent: Wednesday, September 02, 2020 7:24 PM
To: Jim Robertson <jrobertson@desertviewpower.com>
Cc: Connolly, Scott <Connolly.Scott@epa.gov>; TLiebel@aqmd.gov; Kdudash@aqmd.gov; Greg Cook <gcook@greenleaf-power.com>; Mitchell Martin <mmartin@greenleaf-power.com>; AEO_R9 <AEO_R9@epa.gov>; Chew, Andrew <Chew.Andrew@epa.gov>; Ward, Laweeda <WARD.LAWEEDA@EPA.GOV>
Subject: FW: Desert View Power Permit No. CB-OP 99-01 - 10 working day follow up to 48 hr. Notification Excess HCl Emissions. Annual Boiler MACT Compliance Test

Jim,

Can you resend the working link please? Thank you.

- Andrew

Andrew Chew, P.E.
chew.andrew@epa.gov
U.S. EPA, Region 9, Enforcement & Compliance Assurance Division (ECAD), Air Section (ENF-2-1) | 75 Hawthorne St.,
San Francisco, CA 94105

From: Jim Robertson <jrobertson@desertviewpower.com>
Sent: Friday, July 31, 2020 1:22 PM
To: AEO_R9 <AEO_R9@epa.gov>
Cc: Chew, Andrew <Chew.Andrew@epa.gov>; Connolly, Scott <Connolly.Scott@epa.gov>; TLiebel@aqmd.gov; Kdudash@aqmd.gov; Greg Cook <gcook@greenleaf-power.com>; Mitchell Martin <mmartin@greenleaf-power.com>; Jennifer Gavaldon <jgavaldon@greenleaf-power.com>
Subject: Desert View Power Permit No. CB-OP 99-01 - 10 working day follow up to 48 hr. Notification Excess HCl Emissions. Annual Boiler MACT Compliance Test

Per the requirements of PSD Permit SE 87-01 Condition III.C.2.b, please find the attached letter that details a description of circumstances, and probable cause for an excess of HCl that occurred during the Annual Boiler MACT Performance Test. This email is a follow up to the 48 hr. notification that was sent to the EPA on July 24, 2020 (attached).

Below is a link to access the complete final Boiler MACT Compliance Test Results. This link will expire on August 7, 2020.

Ex. 6 Personal Privacy (PP)

If you have any questions, or require any additional information, please do not hesitate to contact me.

Sincerely,

Jim Robertson
Plant Manager
62-300 Gene Welmas Drive
Mecca, CA 92254-0758

Office: 760-262-1682

jrobertson@desertviewpower.com

www.greenleaf-power.com

